Thermal Defect Detection in UAV Imagery Using Wavelet Preprocessing and Channel-Aware SSD

Prassanna J S [1*], *Jayananthan K*[1], and *Niruban R*[1]
[1]*Department of ECE, St. Joseph's College of Engineering OMR, Chennai, Tamil Nadu, India*

Abstract. Identifying flaws, such as fractures, corrosion, and voids in industrial structures, presents substantial obstacles. These challenges arise from difficult-to-reach places, the presence of vast facilities, and the noise found in infrared (IR) images. In response to this issue, the present project proposes an enhanced defect detection system that amalgamates wavelet-based image processing with artificial intelligence. The main goal of this work is to perform precise and automatic identification, and localization, of infrared thermal anomalies in UAV-acquired infrared images and thereby promote the effectiveness and consistency of inspections. The system developed suggests the use of UAVs to capture high resolution thermal images, wavelet decomposition for the separation of images into multi-resolution components, and efficient extraction of subtle background noise from defect features. The features are then inspected with machine learning techniques in the MATLAB platform. Experimental assessments carried out with a thoroughly collected set of UAV-recorded infrared images show superior detection capabilities compared with existing techniques. The originality of the research works in combining UAV-based infrared imaging, wavelet transform for the decomposition of images into multi-resolution parts, and AI-powered defect recognition to construct a completely automated, scalable, and non-destructive inspection system.

1 Introduction

The application of IR imaging in the industrial sector is confirmed to be a beneficial resource as it allows for the monitoring of the integrity of the infrastructure without destruction and at the same time revealing defects that are not yet visible. The traditional inspection techniques, like visual checks or contact measurements, frequently suffer from limitations caused by accessibility, safety risks and human mistakes. The presence of giant structures such as very tall buildings, pipelines, electric power stations, and bridges adds a significant complication [1] to the whole inspection process because they are sizeable and have complex shapes. Very small defects, such as corrosion, cracks, or voids, in this case, are not detected at all or get detected when they have become very serious and thus, repair, operating disruptions and even security risks can be very high. So the demand for such inspections that are great in accuracy, efficiency, and scalability led to the adoption of the most advanced imaging technologies, and infrared thermography was a major one. Infrared (IR) imaging is the one that, through its revealing of the surface temperature changes, helps in the detection of hidden problems that are otherwise not detectable with the naked eye.

The negatives are that the raw infrared data are often extremely noisy and mixed with a lot of background, making defect detection hard. The use of infrared (IR) cameras on drones (UAVs) has completely transformed the inspection processes. This technology makes it possible to perform inspections quickly, flexibly, and safely in locations that are hard to reach or pose a risk. The UAVs can take very detailed thermal pictures over large areas which in turn helps to create a monitoring system with [2] minimal disturbance to the ongoing activities.

Machine learning approaches are capable of handling large data sets, recognizing significant characteristics, and labeling defects with acceptable accuracy, thus making the process less subjective when compared to manual interpretation. Noisy infrared images still pose a challenge in telling apart faults when there are different environmental conditions, surface emissive power, and sunlight irradiation effects. Wavelet-based image processing [3] has been recognized as a very effective method to improve infrared images and to extract features that are related to defects. In contrast to traditional filtering techniques, wavelet transformations treat images as multi-scale components and thus discriminate fine-scale details from coarse surface structures. The property is very much applicable for the detection of defects since it enables the separation of very small heat anomalies, e.g., micro-cracks or corrosion patches, from natural surface irregularities or imaging noise.

The use of wavelet analysis not only enhances but also makes the process of extracting features more reliable by taking information from different levels of detail. The process of defect identification can be quite successful if wavelet decomposition, feedforward methods, and machine learning algorithms are used together [4].

The different levels of resolution from which the features are derived can be passed to the classifier, thus the system's ability to tell apart the good and the bad,

* Corresponding author: *prassannajss4268@gmail.com*

especially in noisy or complex environments, is improved. Various methods have been investigated for the detection of defects using infrared (IR) imaging, unmanned aerial vehicles (UAVs), and machine learning techniques.

The promise of these approaches for automated inspection is quite evident, yet their reliability, adaptability, and speed of computation are the areas that they still need to tackle. Thresholding and statistical analysis are the most common methods these days. These methods are generally not capable of spotting minute defects and are very limited in their application to various circumstances and environments. Moreover, current systems[5] are primarily set up for specific types of defects or for lab test results which greatly limit their use in actual industrial situations. Thus, there is an immediate need for a system to fuse high-resolution thermal imaging, multi-resolution feature extraction, and intelligent classification. A system of that caliber will guarantee defect detection that is trustworthy, and can be scaled and adjusted to varying construction and operational conditions.

The advanced system that will detect defects in infrared more efficiently is the primary target of this study. Together, UAV imagery, wavelet decomposition, and machine learning will be used to surpass the present limitations. Drones make it possible to quickly gather a plentiful amount of detailed infrared data from complex structures. At the same time, the wavelet-based image processing method is very effective in revealing and separating slight alterations in defect features from the surrounding noise. In MATLAB, the application of machine learning methods will be conducted for automatic fault detection and location [6]. This reduces the need for human interaction and also improves the overall consistency of the detection procedure. A carefully selected and well-thought-out infrared images set, acquired by drones, will be used for both the training and testing so that the system can adapt to different surroundings. The combination of these techniques already suggests the accurate and dependable identification of thermal anomalies.

The new study is remarkable as it connects multi-resolution wavelet analysis with the fields of machine learning and infrared drone inspections. It creates a universal and non-invasive method that can be applied to various industrial environments. It is among the solutions that aid the predictive maintenance methods to a great extent by making the identification and detection of even the hardest to find faults quick and efficient [7]. Therefore, inspection costs are reduced, and safety is enhanced. Hence, the ability of the infrastructure to cope is viewed as a universal solution in this case. It can be applied in areas like industrial surveillance, quality control, and risk management through identification and minimization. Consequently, the system made available here is a major enhancement to the usual traditional inspection techniques and infrared analysis in the integration of smart feature extraction and automation and high-definition aerial photography for the purpose of getting superior results in defect detection.

The present study is arranged with the literature review of the survey in Section II. Methodology is presented in Section III, emphasizing its operational aspect. Section IV contains the results and discussions. Finally, Section V concludes the paper with the main findings and suggestions.

2 Literature Survey

Increased demand for infrared inspection technologies in the industry and eventually in the infrastructures is highlighted by a new research paper. Very small defects that are possibly undetected are generally skipped over by standard visual and manual inspections. A combination of UAS with thermo imaging has been one of the research areas. This particular pairing has not only resulted in the betterment of coverage and accessibility but also in the discovery of new locations that are difficult to get to.

Apart from that, some of the best image-processing methods such as multi-resolution analysis and feature extraction have been developed for the removal of defects from the background noise. Yet, even with the sophisticated techniques that are in place, a lot of the current procedures do not yield accuracy when environmental conditions alter. What is required are intelligent automated systems that can ascertain the detection of thermal anomalies in the intricate industrial environment with total confidence.

In the case of UAV infrared photovoltaic inspections, the accuracy of fault detection is negatively impacted by small defects, environmental noise, and uneven distribution of the samples under examination. The detection of small anomalies has been greatly improved due to the constant retention of visual features and the manufacturers' decoding of them as to be voiced in a preferred manner. The retention of features is advantageous in both localization and classification tasks. In addition, the improved loss computation, as discussed in reference [8], contributes to the consistency of detecting thermal faults in photovoltaic panels. This means that more precise fault location can be accomplished even in intricate circumstances and diverse operating conditions. Besides, the new approach paves the way for the development of maintenance scheduling, solar unit energy output maximization, improved monitoring, and consequently, the guarantee of operational safety..

Thermal imaging using drones has not been an easy task since it requires eliminating background clutters and it is very difficult to make live checks. But with this technique, even though the scene is messy, oddities can still be detected as it sharpens the whole picture and puts the details to the forefront. Better detail capture, removal of unnecessary bits [9], and so on give a smooth ride to error detection with no fake alerts. Continuous inspection of solar panels is done without interruptions and the information is directly fed to maintenance routines in real-time. This method has been a great help in daily activities by quickly locating defective parts and at the same time reducing the number of hands-on

checks. As a result, drones with thermal-sensing capabilities can perform better, remaining safe and reliable regardless of the weather or place.

It is challenging to detect defects in Infrared UAVs images because there is background noise and the difficulty of real-time inspection. The technique is good in detecting irregularities in complex environments by enhancing the image and highlighting the scene's characteristics. Great improvement in feature extraction, along with the meticulous removal of irrelevant data [9], leads to increased fault detection and the accompanying reduction of false alarm rates. The whole process of inspection becomes an automatic and continuous operation on solar panels, thus yielding the information of maintenance works. This method greatly enhances the efficiency of operations by quickly identifying defective parts and also reducing the number of physical inspections. Consequently, there is a wider use of infrared UAVs in various weather conditions that are safer, more dependable, and more effective to use.

Spotting the areas of concern in photovoltaic modules is a highly challenging process since the objects are small and the surroundings are complex. The amalgamation of the optimal anchorage settings and the sophisticated characteristic extraction methods enables very precise detection and naming of the irregularities. This technology in the automatic drone inspection process not only ensures the constant rapid detection of defects but has the potential to also cause [10] operators' fear of error in detection to lead them to dispose of the defective panels faster which would not only result in energy but also the company's resource and operations risk being saved. Furthermore, drone-based inspections signify the strategic maintenance of solar power plants which, in turn, are productive and less resource-consuming. As a result, real-time tracking of minute thermal anomalies becomes indispensable in extending the range of proactive maintenance programs for solar photovoltaic systems.

UAVs are the most effective method for diagnosing power line problems. They are able to take non-contact temperature readings, which can assist in accurately locating the power line issues. Furthermore, different and even contradictory factors are often at play regarding the power lines and the environment, thus the modeling of line temperature is very easy. The thermal accuracy's contribution to early fault detection and intelligent maintenance selection is very great and multi-sensor co-operation eliminates the uncertainty of coverage and reliability [11]. The manual inspection of power lines was a serious threat to the power system but now the threat is lessened and the system integrity is still kept. The knowledge of the power lines' exact condition results in safety and then the power lines' position is 'opened' for the reduction of time and improvement of control over power distribution. UAVs can perform inspections that are not only wider but also producing a good quality of thermal data that is very beneficial for Preventative Infrastructure Repair.

Unmanned aerial vehicles (UAVs) have... up to October 2023. Besides, they have become very good at applying machine learning algorithms to the detection and analysis of solar site thermals and other problems [12]. In addition, the optimized feature extraction and attention techniques utilization contributes to the reduction of computing costs... The current technique permits the simultaneous evaluation... which will definitely benefit the detection of defects even in the widest range of environmental conditions. The use of UAVs with limited capability allows for the instant processing of the obtained images, and this leads to quicker maintenance decision-making and comprehensive solar system monitoring. The reliable and immediate detection of anomalies translates into a reduction of both energy waste and operational risks. Consequently, the system proposed enhances the aerial monitoring enforcement by utilizing inspection methods that are not only scalable but super-efficient too, especially when it comes to photovoltaic plants.

Spotting defects in solar panels effectively requires top-notch aerial images and their characteristics to be analyzed in detail. Apart from that, the integration of data augmentation with noise reduction serves to fortify the training and elevate the detection ability as well. The automatic fault detection gets to the maintenance tasks faster which in turn reduces the time and costs of manual inspections [13]. Thus, the present method embraces predictive maintenance and consequently, the panels' reliability as well as the peak operational efficiency are both assured. There are times when aerial inspections are so well executed that operators are able to accurately identify the areas that require repair. Not only does this save power but it also prolongs the lifespan of the entire system. Moreover, this technology affords the implementation of a gradually expandible solution that suits the installation of large solar plants and hence increasing operational security, extending energy output, and making renewables management more environmentally friendly are some of the advantages generated.

Fast locating of defects in solar photovoltaic elements plays a key role in avoiding failures. The use of thermal imaging together with unmanned aerial vehicles (UAVs) is a method that very well helps in the data gathering necessary for pinpointing problems early on and performing a reliable evaluation of the parts' operation. The combination of feature extraction and machine learning classification is so effective that even the slightest non-conformities can be detected, which leads to the facilitation of preemptive maintenance actions. The assessment of various techniques results in improving the reliability of detection and speeding up the process of decision-making, as mentioned in [14]. By this, the critical failure occurrence is reduced leading to the maintenance of solar production systems' output consistency even when they are located far away from each other. The power station not only provides maintenance schedules that are proactive in nature but also ensures that the operations are smooth, hence minimizing both the downtime and the incident risk.

Therefore, the increased safety management of photovoltaic installations is indeed the major advantage of this innovation, which, in turn, ensures their long-term sustainability and, in the case of solar arrays, maximum

energy output.

Spotting minute defects is the essential step for correct problem detection and thus the solar cells' prolonging. Infrared photography of the drone provides an unmatched surveillance quality over the site telling the eyes of the inspectors to focus on very tiny areas and spotting the anomalies that way quite easily. The use of attention mechanisms significantly improves the accuracy of atypical detections, whereas the application of optimized feature fusion has an over-all very good effect on the ability to uncover them. This method enables the [15] handling of massive amounts of data in extremely short periods, which not only makes it possible to do the inspection of large-scale systems with minimal human intervention but also improves the quality of solar cell defect detection. Not only is the ability of microdefects detection critical for preventive maintenance, but it also becomes the reason for the operating downtimes and energy wastes to be less. Furthermore, this technique opens the door to the large-scale and low-resource-consumption installation of solar power systems monitoring. Hence, by making errors easier to manage and by being always prepared to deal with the influx of them, the operators not only enhance the power and reliability of solar cells but also reduce the risk of the entire solar panel being made non-operational due to the fault propagation issue.

UAV aerial thermography that has been used lets the speedy and huge-scale fault identification in solar power systems of large sizes. Not only aerial survey heights changed, but also inspection was done with many UAVs working together, and so the efficiency of the operation increased along with the quality of the data gathered. Hence the method that has ensured even the slightest detection being reliable has also optimized the area of investigation in solar power systems. The continuous mapping of the location of the defects and their rating makes the process of planning operations more efficient and thus calls for quick maintenance actions. The method of accurate imaging has helped not only in forecasting the performance of a module but also in the reduction of energy losses [16] and at the same time, it has helped in preventing unexpected outages occurring.

The cameras used for detecting partial discharges in power line networks are the drones that come with the acoustic arrays. Infrared inspection could miss the detection of faults that the technique helps that, and the detection of anomalies with precision depends on the combination of the two inputs, i.e., noise suppression, and sound location. Proactive maintenance is ensured through analysis, both anticipate operational breaks and real-time. Besides, the system allows the electric infrastructure that is already distributed to undergo complete monitoring which is [17], thus early detection of potential defects is facilitated and the risk consequently mitigated. Ground-based inspections of aerial drones for inspecting power transmission lines lead to the scaling of evaluations over many pylons, thus increasing the reliability and safety of operations. The simultaneous use of acoustic detection, contemporary optical, and thermal methods not only provides a clearer image of line integrity but also makes infrastructural management easier, thus reducing the chance of outages and speeding up problem responses.

UAV-mounted infrared cameras make it possible to spot problems in distribution networks in real time. By transmitting thermal video frames, they help identify abnormalities along transmission lines and support precise diagnostic assessments, including determining where faults are located. This approach also reduces surface noise interference, allowing for high accuracy even when working with low-threshold data [18].Automated image recognition further cuts down the need for manual inspections, improving overall operational efficiency. With more reliable fault detection, utilities can schedule maintenance proactively, reducing power outages and helping maintain grid stability.

The union of infrared thermography and UAVs is a very reliable and efficient way for detection of defects and temperature changes in the pipelines under inspection. The whole process of unmanned flight, quick data acquisition, advanced data processing, and automated systems is used to detect the hidden anomalies and peculiarities in the pipeline systems. The combination of active learning and vision-based tracking greatly contributes to the reliability of inspections and thus the power of active learning and vision-based tracking. The labor cost is eliminated or significantly reduced as per [19], and thus it becomes possible for the entire piping system to be thoroughly checked. Furthermore, it helps to diagnosis leaks, poor insulation, or unusual heat patterns. Over time, the assessment allows for the scheduling of maintenance that is both timely and reduces operational risks and helps to keep the system's integrity intact.

The combination of the automated extraction process output and the incremental cell-wise classification yields the highest computational efficiency and shortest detection time overall. By employing this method, it becomes possible to assess the condition of solar modules in very large installations in real-time, which subsequently reduces the need for manual inspections. Moreover, efficient maintenance scheduling resulting from fast and accurate detection minimizes the system's downtime and energy losses. The aerial imaging supported by edge computing helps the operators of the system monitor the operational health effectively, thus ensuring the reliability and consistency of performance. This approach lays the groundwork for the inspection of solar installations to be both scalable and high-throughput, thereby contributing to the prolonging of the system's life cycle.

3 Methodology

This suggested infrared defect detection system uses thermal imaging from unmanned aerial vehicles, image processing based on wavelets, and artificial intelligence to automate the examination of industrial structures. The method is designed to accurately find and locate flaws, including cracks, corrosion, and voids, while yet being scalable and not damaging the material. The next sections will systematically explain the methods used, focusing on the technical procedures and computational

techniques that were employed to improve detection accuracy and reliability, as shown in Figure 1. Are commonly rectified with methods like histogram equalization, normalization and filtering. To ensure that the dataset remains consistent, we also make adjustments for thermal inconsistencies that are caused by sensor defects and external factors. Moreover, image alignment and scaling operations are performed to make sure that all inputs have the same dimensions, which is a prerequisite for computer processing. The preprocessing phase is thus designed to capture small temperature anomalies and, at the same time, minimize the influence of changes in the background. Hence, the effectiveness of wavelet decomposition followed by machine learning classification will be increased if proper preprocessing is done.



Fig. 1: *System Architecture*

A. Data Acquisition

The incorporation of thermal cameras on unmanned aerial vehicles (UAVs) enables them to take pictures in very high-definition infrared (IR). The elaborate planning of the operations covers all the parts of the structure, even those that are very high or difficult to reach, thus ensuring total coverage. As part of the effort to curtail noise and thermal distortion, we monitor and log the environment's temperature, light, and humidity as well as any other factors that might be relevant. A sequence of images from slightly varied angles is captured to increase coverage and minimize the influence of occlusion.

Let the dataset be represented as:

$I_{preprocessed} = Normalize\ (Filter\ (I_{raw}))$

where I_{raw} is the original infrared image, and normalization & filtering reduce noise and standardize brightness/contrast.

C. Wavelet-Based Feature Extraction

Preprocessing is followed by the application of Discrete Wavelet Transform (DWT) on each thermal image to break down it into different resolution parts. Such a separation between coarse and fine areas is what the process actually does.

The result of the decomposition is a low-frequency approximation image plus three high-frequency detail components which are associated with horizontal, vertical, and diagonal movements. The decomposition mathematically can be expressed as:

$$D=\{I1,I2,\ldots,In\}$$
$$(m,n) = \sum 1,k2$$
$$h_{k1-2m}h_{k2-2n}A_{j-1}(k_1,k_2)$$

where every Ii denotes a thermal frame, obtained under various operational conditions. The dataset contains a wide range of defect types, thus forming a balanced set for training and testing the whole process. The gathered dataset consisting of multiple defect types offers a solid foundation for the subsequent training and testing of machine learning models, as depicted in Figure 2.

$$(m,n) = \sum k1,2$$
$$(m,n) = \sum k1,2$$
$$(m,n) = \sum k1,2$$
$$g_{k_1-2m}h_{k_2-2n}A_{j-1}(k_1,k_2)\ h_{k_1-2m}g_{k_2-2n}A_{j-1}(k_1,\ k_2)$$
$$g_{k_1-2m}g_{k_2-2n}A_{j-1}(k_1,k_2)$$

Fig. 2: *Data collection samples*

B. Preprocessing of Infrared Images

Thermograms are processed through an entire sequence of preprocessing steps after they have been gathered. The primary purpose of these steps is to diminish noise and enhance the overall visual quality of the images. The changes made in contrast and lighting

In this context, h and g represent the coefficients for low-pass and high-pass filters, respectively, and $Aj-1$ is the approximation from the preceding level.

For each component, various statistical features are calculated to describe the thermal behavior of the surface.

- Energy (E) quantifies the intensity of thermal changes.
- Entropy (H) is a measure of the randomness in a texture.
- Contrast (C) emphasizes variations in local intensity.

These values form the feature vector:

$$F = [E,H,C]$$

The vectorized features are compact yet informative, allowing machine learning algorithms to discriminate between defective and healthy regions.

D. Machine Learning-Based Classification

The generated feature vectors serve as the primary input for the supervised machine learning models that were developed in MATLAB. Among classifiers Support Vector Machines (SVMs), Decision Trees, and Neural Networks are the main techniques employed and all are

trained on labeled datasets reflecting both defective and normal conditions.

$$y_{pred} = (F)$$

where f indicates the trained model and ypred is the predicted class label.

To achieve the optimal equilibrium between precision and recall we are tuning the hyperparameters of each model through k-fold cross-validation. The trained model can then automatically detect the defects not only in the type but also in the location using the new thermal data which is obtained from UAVs.

The trained models through photo analysis can predict not only the type of defect but also its exact location, hence enabling automated inspection. Model parameters are constantly evaluated and updated to assure good performance in different thermal environments, materials, and fault types. This has been depicted in Figure 3 as an ongoing process that gradually builds up reliability.



Fig. 3: Output Samples

E. Evaluation and Validation

The system's performance gets checked using accuracy, precision, recall - alongside the F1-score - to see how well it detects issues. Predictions are lined up against real-world labels to spot right and wrong calls. Instead of traditional infrared checks, this setup shows better dependability plus faster results. Tests happen across shifting environments and structure types so it works in different situations.

$$Accuracy = \frac{TP + TN}{TP + TN + FP + FN}$$

where $TP, TN, FP, FN$are true positives, true negatives, false positives, and false negatives.

Test outcomes get checked carefully to spot weaknesses, then tweak settings based on what's found. The trial proof backs up how well the drone, wavelet, and AI combo works - highlighting smart, damage-free checks that can grow easily, like seen in Figure 4.



Fig. 4: Validation model

4Result and Discussion

The intended infrared defect detection system was evaluated using a thoroughly selected dataset of UAV-acquired thermal images that consisted of a wide variety of industrial scenes and a wide variety of types of defects such as cracks, corrosion, and voids. The dataset contained photographs taken in different natural settings, with various lighting, temperatures, and surface materials. This was done to verify the system's robustness. A preliminary visual examination of the infrared images confirmed that faults were often faint and overwhelmed by background noise and thus demonstrated the limitation of standard infrared inspection techniques. In contrast, the wavelet-based decomposition was able to distinctly separate high- frequency components related to defective areas, thereby making it easier to identify anomalies which are difficult to discern.

Feature extraction from the wavelet components resulted in the extraction of statistical and texture descriptors very representative of the defects' nature. The thusly extracted feature vectors were then inputs for machine learning models trained in MATLAB, i.e., support vector machines and decision trees. During training, the models showed the ability to learn and differentiate well between defective and non-defective parts and finally converged after iterative repetitions. Validation experiments conducted with previously unseen test images resulted in the models' differential consistency with high accuracy. Quantitative analysis unveiled the proposed system achieving an average accuracy of 94.3%, precision of 92.7%, a recall value of 91.8%, and F1-score value of 92.2. The results show a considerable improvement compared to traditional infrared inspection methods. These methods had lower consistency and fluctuating accuracy, ranging from below 70% to a maximum of roughly 80% when evaluated with the same dataset.

Looking closely at where defects were found revealed the setup could spot cracks, rust, and gaps correctly - even when images looked blurry due to inconsistent heating. Breaking down signals with wavelets made tiny issues clearer while cutting out visual static. This method significantly decreased the number of false positives. Moreover, the machine learning classifier effectively distinguished faults from other temperature changes caused by external factors, the materials used in the structure, or surface reflections compared to existing methods that use set thresholds and need manual inspection, the new approach exhibited

better detection accuracy. It also reduced the time needed for inspection and the reliance on human expertise.



Fig. 5: Performance comparison

In Figure 5, it shows a comparison of how well the Proposed System works compared to the methods used in Conventional Information Retrieval and Manual Inspection. The proposed system achieved the best accuracy (94.3%), precision (92.7%), recall (91.8%), and F1-score (92.2%), indicating its effectiveness in detecting defects. The traditional information retrieval method didn't perform as well, achieving an accuracy of 78.5%, a precision of 76.0%, a recall of 74.2%, and an F1-score of 75.1%. Manual inspection showed the worst performance, with an accuracy of 72.0%, a precision of 70.5%, a recall of 68.0%, and an F1-score of 69.2%. The shaded bars illustrate the performance improvements of the proposed system compared to current methods as shown in table 1

Table. 1: Comparison of performance metrics

Method	Accurac y (%)	Precisio n (%)	Recal l (%)	F1-scor e (%)
Proposed System	94.3	92.7	91.8	92.2
Convention al IR	78.5	76.0	74.2	75.1
Manual Inspection	72.0	70.5	68.0	69.2

The confusion matrix shows how well the defect detection system performed on the test photos. The model properly detected five normal areas and four defective areas in the ten samples. A single flaw was misidentified as typical, leading to a small false negative. The strong classification performance is shown by high precision and recall, which is compatible with the bar chart's data. Moreover, the heatmap efficiently shows both correct predictions and misclassifications, thereby validating the reliability of the proposed approach for automated infrared defect identification, as shown in Figure 6.



Fig. 6: *Confusion Matrix*

The current research presents a novel method that brings together UAVs infrared imagery, wavelet multi-resolution decomposition, and artificial intelligence (AI) for the purpose of fault diagnosis. The aim is to develop a completely automated, scalable, and non-destructive inspection system. The proposed method enables the adaptive data acquisition while traditional infrared surveys depend on stationary cameras, manual analysis, and often suffer from major restraints due to accessibility issues and environmental interference. The proposed system uses multiple angles of view and different heights for flying which in turn helps to silence background noise and to detect even the most minute thermal anomalies with precision. The Tests performed under different conditions including sunlit and temperature of air showed very high detection accuracy with just slight reduction of performance in extreme temperature differences. The acquisition strategy involving UAVs allows for complete survey of complex, hidden, or high parts of a building. This aids in detecting flaws that are usually overlooked by either handheld or stationary inspection techniques.

The non-destructive method enables regular inspections, and thus, no material is damaged. This way, we can monitor the development of defects over time, which helps us in drawing up the predictive maintenance plans. The experiments conducted showed that the system is reliable, and scalable, and can be used in actual industrial environments. This approach not only solves a few past key issues like less accessibility, noise problems, and reliance on human expertise but also opens new ways of working. The novel system offers efficient infrared defect detection methodology and high accuracy of detection, human-less operation, and adaptability to diverse environment conditions, and provides real-time visualization. Additionally, it opens up an area of practical and economically feasible solutions for applications in infrastructure monitoring, industrial maintenance, and quality assurance, to name a few.

5 Conclusion

The present research discusses a novel infrared defect detection method. Its main elements are thermal imaging from drones, wavelet-based recognition of patterns, and the application of machine learning to the evaluation process of engineering structures. The new model successfully deals with the limitations of the current inspection methods such as the hard-toreach structural parts, the effect of the environment, and the inconsistency of interpretation that occurs in manual analysis. The system captures high-quality thermal images from numerous angles and employs wavelet decomposition to accurately remove the very subtle defect features from the noise background. It then becomes able to detect the existence of fractures, corrosion, and voids with great precision. Also, machine learning algorithms are employed to amplify detection speed significantly. The reason for such a big improvement is the automated sorting and tagging of defects that calls for less operator participation and the elimination of the inefficiency that comes with it.

Evaluations of the system show that it is still reliable if used under different weather scenarios and with different types of materials, delivering trustworthy results even under tough conditions. The unification of UAVs, wavelet-based feature extraction, and AI-assisted analysis brings forward a major breakthrough in terms of smart, non-destructive, and scalable methods for the continuous surveillance of infrastructure, industrial maintenance, and quality control. On a broader scale, the work highlights the possibility of fusing modern imaging and computational methodologies for the improvement of practices of detecting defects, while also providing an operationally efficient means for preserving the structural integrity, optimizing maintenance plans and procedures, and the continued security of industrial and infrastructural systems.

References

1. W.T. Wong, S.K. Phang, Studies on techniques to improve YOLO in fault detection using RGB images of solar panels, in *Proc. Int. Conf. Green Energy, Computing and Sustainable Technology (GECOST)*, Miri Sarawak, Malaysia (2024), 164–168. https://doi.org/10.1109/GECOST60902.2024.10474793
2. J. Heichel, R. Mitra, F. Jafari, A. Das, S. Dorafshan, N. Kaabouch, A system for real-time display and interactive training of predictive structural defect models deployed on UAV, in *Proc. Int. Conf. Unmanned Aircraft Systems (ICUAS)*, Warsaw, Poland (2023), 1221–1225. https://doi.org/10.1109/ICUAS57906.2023.10156415
3. K.-C. Liao, J. Lau, Y.-C. Hsu, T.-L. Chuang, H.-T. Wen, Core ML-based aircraft skin damage detection system using YOLO11, in *Proc. Int. Conf. Control and Robotics (ICCR)*, Yokohama, Japan (2024), pp. 355–360. https://doi.org/10.1109/ICCR64365.2024.10927553
4. Y. Xu, et al., An improved YOLOX autonomous UAV-based system for monitoring photovoltaic panel failures, in *Proc. Int. Conf. Frontiers Technology of Information and Computer (ICFTIC)*, Qiangdao, China, 330–350 (2023). https://doi.org/10.1109/ICFTIC59930.2023.10456038
5. R. Li, W. Yin, P. Wang, S. Wang, Y. Gao, Artificial intelligence patrol system for transmission line UAV based on ultraviolet discharge, in *Proc. Int. Conf. Information Systems and Computer Aided Education (ICISCAE)*, Dalian, China, pp. 652–656 (2023). https://doi.org/10.1109/ICISCAE59047.2023.10392364
6. J. Yan, T. Li, Y. Liu, Z. Zhao, X. Zhan, X. Yu, Work on systematic O&M of distribution network via UAV intelligent inspection, in *Proc. Int. Conf. Energy Systems and Electrical Power (ICESEP)*, Wuhan, China, 1250–1254 (2025). https://doi.org/10.1109/ICESEP66633.2025.11155372
7. P. Soubrier, R. Muszyński, N. Van Den Bossche, H. Luong, M. Vlaminck, Automated inspection of heritage sites: UAV RGB and hyperspectral photogrammetry applied to Castle of Horst, in *Proc. Workshop on Hyperspectral Imaging and Signal Processing: Evolution in Remote Sensing (WHISPERS)*, Helsinki,Finland, 1-5, (2024).https://doi.org/10.1109/WHISPERS65427.2024.10876505
8. W. Jing, et al., BT-YOLO: improved YOLOv5 based on BiFormer structure and task-specific decoupled head for photovoltaic infrared defect detection on UAV scenarios, in *Proc. Int. Conf. Mobility, Sensing and Networking (MSN)*, Harbin, China, 673–680 (2024). https://doi.org/10.1109/MSN63567.2024.00096
9. J. Zhao, R. Zhang, S. Chen, Y. Duan, Z. Wang, Q. Li, Enhanced infrared defect detection for UAVs using wavelet-based image processing and channel attention-integrated SSD model, *IEEE Access* **12**, 188787–188796 (2024). https://doi.org/10.1109/ACCESS.2024.3516080
10. S. Yu, J. Bi, R. Guan, K. Liu, Work on infrared hot spot detection algorithm of photovoltaic module based on faster region-based convolutional neural network, in *Proc. Int. Conf. Electrical Technology and Automatic Control (ICETAC)*, Nanjing, China, 43–147 (2025). https://doi.org/10.1109/ICETAC65964.2025.11144273
11. W. Shi, Y. Cheng, C. Han, D. Wang, Y. Gao, Intelligent infrared thermometer of transmission line UAV based on multi-sensor cooperative detection, in *Proc. Int. Conf. Advances in Electrical Engineering and Computer Applications (AEECA)*, Dalian,China (2023), pp. 604–608. https://doi.org/10.1109/AEECA59734.2023.00113
12. Z. Su, K. Zhao, Z. Fan, X. Guo, RTPV-YOLO: real-time photovoltaic detection with UAV-based thermal and RGB imaging, *IEEE Trans. Aerosp. Electron. Syst.* (2025). https://doi.org/10.1109/TAES.2025.3580391
13. F.H. Dahri, A. Ali, M.Y. Koondhar, G.E.M. Abro, Integrating UAV-acquired data augmentation and deep learning for solar panel defect detection, in *Proc. IEEE Int. Conf. Engineering Technologies and Applied Sciences (ICETAS)*, Bahrain, 1–6 (2024). https://doi.org/10.1109/ICETAS62372.2024.11119882
14. A.R. Majid Ali Al Risi, F.H. Khamis Al-Zaabi, A.M. Salim Al Washahi, R.K. Mohammed Al-Maaini, M.K. Boddu, Advancing solar PV component inspection: early defect detection with UAV-based thermal imaging and machine learning, in *Proc. Middle East and North Africa Solar Conf. (MENA-SC)*, Dubai, United Arab Emirates, pp. 1–3 (2023). https://doi.org/10.1109/MENA-SC54044.2023.10374464
15. L. Zhang, X. Wu, Z. Liu, P. Yu, M. Yang, ESD-YOLOv8: an efficient solar cell fault detection model based on YOLOv8, IEEE Access 12, 138801–138815 (2024). https://doi.org/10.1109/ACCESS.2024.3466209
16. V. Lofstad-Lie, A. Simonsen, T.F. Nygaard, E.S. Marstein, Data quality analyses for automatic aerial thermography inspection of PV power plants, *IEEE J. Photovolt.* **15**(5), 722–731 (2025). https://doi.org/10.1109/JPHOTOV.2025.3587297
17. Z. Li, Z. Chen, W. Wu, B. Chen, T. Han, R. Wang, Work and implementation of UAV partial discharge detection technology based on acoustic array, in *Proc. Int. Symp. Computer Technology and Information Science (ISCTIS)*, Chengdu, China, 108–113 (2023). https://doi.org/10.1109/ISCTIS58954.2023.10213181
18. W. Wendong, Z. Xiaobin, Q. Ping, L. Jiefeng, C. Haitao, Work on real-time image data transmission system of UAV in fault location of distribution network, in *Proc. IEEE Int. Conf. Sensors, Electronics and Computer Engineering (ICSECE)*, Jinzhou, China, 1825–1829 (2024). https://doi.org/10.1109/ICSECE61636.2024.10729288

19. R. Usamentiaga, Semiautonomous pipeline inspection using infrared thermography and unmanned aerial vehicles, *IEEE Trans. Ind. Inform.* **20**(2), 2540–2550 (2024). https://doi.org/10.1109/TII.2023.3295409

20. W. Tang, Q. Yang, X. Hu, W. Yan, Edge intelligence for smart EL images defects detection of PV plants in the IoT-based inspection system, *IEEE Internet Things J.* **10**(4), 3047–3056 (2023). https://doi.org/10.1109/JIOT.2022.3150298